

<b>ID #</b>	<b>Address</b>	<b>Street</b>	<b>Damage Assessment</b>
221	7301	Adana	Siding / Antenna
222	7305	Adana	Door / Windows
223	7309	Adana	ok
224	7313	Adana	Screen
225	7317	Adana	Skirting
226	7321	Adana	Siding / Skirting
227	7325	Adana	ok
228	7329	Adana	ok
229	7333	Adana	ok
230	7337	Adana	ok
231	7341	Adana	Skirting
241	7344	Adana	Roof
232	7345	Adana	ok
240	7348	Adana	Shutter
233	7349	Adana	ok
239	7352	Adana	Skirting
234	7353	Adana	Skirting
238	7356	Adana	Skirting

<b>ID #</b>	<b>Address</b>	<b>Street</b>	<b>Damage Assessment</b>
235	7357	Adana	ok
237	7360	Adana	ok
236	7361	Adana	ok
119	7427	Arbela	Tree
118	7428	Arbela	Shutter
120	7431	Arbela	Tree
117	7432	Arbela	ok
121	7435	Arbela	Tree
116	7436	Arbela	Shutter
122	7439	Arbela	Tree
115	7440	Arbela	ok
123	7443	Arbela	ok
114	7444	Arbela	ok
124	7447	Arbela	Tree
113	7448	Arbela	Roof
125	7451	Arbela	Fence / Skirting
112	7454	Arbela	Screen
126	7455	Arbela	Facia
127	7459	Arbela	Screen
111	7460	Arbela	Tree
128	7463	Arbela	ok
110	7466	Arbela	ok
129	7467	Arbela	Tree

<b>ID #</b>	<b>Address</b>	<b>Street</b>	<b>Damage Assessment</b>
<b>349</b>	<b>7372</b>	<b>Beckley</b>	ok
<b>327</b>	<b>7373</b>	<b>Beckley</b>	Skirting
<b>348</b>	<b>7376</b>	<b>Beckley</b>	ok
<b>328</b>	<b>7377</b>	<b>Beckley</b>	ok
<b>347</b>	<b>7380</b>	<b>Beckley</b>	ok
<b>329</b>	<b>7383</b>	<b>Beckley</b>	ok
<b>346</b>	<b>7384</b>	<b>Beckley</b>	ok
<b>330</b>	<b>7387</b>	<b>Beckley</b>	ok
<b>345</b>	<b>7388</b>	<b>Beckley</b>	ok
<b>331</b>	<b>7391</b>	<b>Beckley</b>	ok
<b>344</b>	<b>7392</b>	<b>Beckley</b>	ok
<b>332</b>	<b>7395</b>	<b>Beckley</b>	ok
<b>343</b>	<b>7396</b>	<b>Beckley</b>	Screen
<b>333</b>	<b>7399</b>	<b>Beckley</b>	ok
<b>342</b>	<b>7400</b>	<b>Beckley</b>	ok
<b>334</b>	<b>7403</b>	<b>Beckley</b>	ok
<b>341</b>	<b>7404</b>	<b>Beckley</b>	ok
<b>335</b>	<b>7407</b>	<b>Beckley</b>	ok
<b>340</b>	<b>7408</b>	<b>Beckley</b>	ok
<b>336</b>	<b>7411</b>	<b>Beckley</b>	ok
<b>339</b>	<b>7412</b>	<b>Beckley</b>	ok
<b>337</b>	<b>7415</b>	<b>Beckley</b>	Siding
<b>338</b>	<b>7416</b>	<b>Beckley</b>	ok

<b>ID #</b>	<b>Address</b>	<b>Street</b>	<b>Damage Assessment</b>
<b>536</b>	<b>7300</b>	<b>Candace</b>	ok
<b>537</b>	<b>7301</b>	<b>Candace</b>	ok
<b>535</b>	<b>7304</b>	<b>Candace</b>	Lanai / Shutter / Debris
<b>538</b>	<b>7307</b>	<b>Candace</b>	ok
<b>534</b>	<b>7308</b>	<b>Candace</b>	Gutters & Downspouts
<b>533</b>	<b>7312</b>	<b>Candace</b>	ok
<b>539</b>	<b>7313</b>	<b>Candace</b>	Lattice / Carport
<b>532</b>	<b>7316</b>	<b>Candace</b>	ok
<b>540</b>	<b>7317</b>	<b>Candace</b>	Tree down / Car Cover off
<b>531</b>	<b>7320</b>	<b>Candace</b>	ok
<b>541</b>	<b>7321</b>	<b>Candace</b>	ok
<b>530</b>	<b>7324</b>	<b>Candace</b>	ok
<b>542</b>	<b>7325</b>	<b>Candace</b>	ok
<b>529</b>	<b>7328</b>	<b>Candace</b>	ok
<b>543</b>	<b>7329</b>	<b>Candace</b>	ok
<b>528</b>	<b>7332</b>	<b>Candace</b>	Tree / Debris
<b>544</b>	<b>7333</b>	<b>Candace</b>	ok
<b>527</b>	<b>7336</b>	<b>Candace</b>	ok
<b>526</b>	<b>7340</b>	<b>Candace</b>	ok
<b>525</b>	<b>7344</b>	<b>Candace</b>	ok
<b>524</b>	<b>7348</b>	<b>Candace</b>	ok
<b>523</b>	<b>7352</b>	<b>Candace</b>	ok
<b>522</b>	<b>7356</b>	<b>Candace</b>	ok
<b>521</b>	<b>7360</b>	<b>Candace</b>	ok
<b>520</b>	<b>7364</b>	<b>Candace</b>	ok
<b>511</b>	<b>7365</b>	<b>Candace</b>	ok
<b>519</b>	<b>7368</b>	<b>Candace</b>	ok
<b>512</b>	<b>7369</b>	<b>Candace</b>	ok
<b>518</b>	<b>7372</b>	<b>Candace</b>	ok
<b>513</b>	<b>7373</b>	<b>Candace</b>	ok
<b>517</b>	<b>7376</b>	<b>Candace</b>	ok
<b>514</b>	<b>7377</b>	<b>Candace</b>	ok
<b>516</b>	<b>7380</b>	<b>Candace</b>	Tree / Debris
<b>515</b>	<b>7381</b>	<b>Candace</b>	ok

<b>ID #</b>	<b>Address</b>	<b>Street</b>	<b>Damage Assessment</b>
378	7450	Danvers	ok
434	7451	Danvers	Skirting
379	7454	Danvers	ok
433	7455	Danvers	ok
380	7458	Danvers	Awning
432	7459	Danvers	Screens
431	7463	Danvers	ok
381	7464	Danvers	ok
430	7467	Danvers	ok
382	7470	Danvers	Roof / Lanai
429	7471	Danvers	ok
383	7474	Danvers	Tree Down
428	7475	Danvers	Skirting & a lot of debris
384	7478	Danvers	Siding
427	7479	Danvers	Skirting
426	7483	Danvers	ok
385	7484	Danvers	ok
425	7487	Danvers	ok
386	7490	Danvers	ok
424	7491	Danvers	ok
387	7494	Danvers	Siding
423	7495	Danvers	ok
388	7498	Danvers	Roof
422	7499	Danvers	Roof
389	7502	Danvers	ok
421	7503	Danvers	Fence
390	7506	Danvers	ok
391	7510	Danvers	ok
392	7514	Danvers	Siding & Skirting
393	7518	Danvers	ok
394	7522	Danvers	ok
395	7526	Danvers	Skirting
420	7527	Danvers	ok
396	7530	Danvers	ok
419	7531	Danvers	ok

<b>ID #</b>	<b>Address</b>	<b>Street</b>	<b>Damage Assessment</b>
<b>397</b>	<b>7534</b>	<b>Danvers</b>	Skirting
<b>418</b>	<b>7535</b>	<b>Danvers</b>	ok
<b>417</b>	<b>7539</b>	<b>Danvers</b>	ok
<b>398</b>	<b>7540</b>	<b>Danvers</b>	Screens
<b>416</b>	<b>7543</b>	<b>Danvers</b>	ok
<b>399</b>	<b>7546</b>	<b>Danvers</b>	Siding
<b>415</b>	<b>7547</b>	<b>Danvers</b>	Siding
<b>400</b>	<b>7550</b>	<b>Danvers</b>	Windows & Skirting
<b>414</b>	<b>7551</b>	<b>Danvers</b>	ok
<b>401</b>	<b>7554</b>	<b>Danvers</b>	Siding
<b>413</b>	<b>7555</b>	<b>Danvers</b>	ok
<b>412</b>	<b>7559</b>	<b>Danvers</b>	Roof
<b>402</b>	<b>7560</b>	<b>Danvers</b>	ok
<b>411</b>	<b>7563</b>	<b>Danvers</b>	Screens
<b>403</b>	<b>7566</b>	<b>Danvers</b>	ok
<b>410</b>	<b>7567</b>	<b>Danvers</b>	Mailbox
<b>404</b>	<b>7570</b>	<b>Danvers</b>	Siding
<b>409</b>	<b>7571</b>	<b>Danvers</b>	ok
<b>405</b>	<b>7574</b>	<b>Danvers</b>	ok
<b>408</b>	<b>7575</b>	<b>Danvers</b>	Fence
<b>406</b>	<b>7578</b>	<b>Danvers</b>	Skirting
<b>407</b>	<b>7579</b>	<b>Danvers</b>	Skirting

<b>ID #</b>	<b>Address</b>	<b>Street</b>	<b>Damage Assessment</b>
279	7300	Desant	ok
278	7304	Desant	ok
256	7305	Desant	Lattice / Siding
277	7308	Desant	Trellils
276	7312	Desant	ok
257	7313	Desant	ok
275	7316	Desant	ok
258	7317	Desant	Tree / Skirting
274	7320	Desant	Flashing off back
259	7321	Desant	ok
273	7324	Desant	Carport Roof / Screen / Antenna down
260	7325	Desant	Downspout
272	7328	Desant	ok
261	7329	Desant	Roof has bricks on it / Shutters off
271	7332	Desant	Fence
262	7333	Desant	ok
270	7336	Desant	ok
263	7337	Desant	ok
269	7340	Desant	ok
264	7341	Desant	Fruit tree
268	7344	Desant	ok
265	7345	Desant	ok
267	7348	Desant	Front storm shutter / Fence
266	7349	Desant	Palm tree

<b>ID #</b>	<b>Address</b>	<b>Street</b>	<b>Damage Assessment</b>
71	7474	Fulmar	ok
72	7478	Fulmar	ok
73	7482	Fulmar	ok
74	7486	Fulmar	Golf Cart Cover
75	7490	Fulmar	ok
76	7494	Fulmar	ok
77	7498	Fulmar	ok
78	7502	Fulmar	ok
79	7506	Fulmar	ok
88	7507	Fulmar	ok
80	7510	Fulmar	ok
87	7511	Fulmar	ok
81	7514	Fulmar	ok
86	7515	Fulmar	ok
82	7518	Fulmar	ok
85	7519	Fulmar	ok
83	7522	Fulmar	ok
84	7523	Fulmar	ok



<b>ID #</b>	<b>Address</b>	<b>Street</b>	<b>Damage Assessment</b>
255	7324	Hedwig	ok
242	7325	Hedwig	ok
254	7328	Hedwig	ok
243	7331	Hedwig	ok
253	7332	Hedwig	Skirting
252	7336	Hedwig	ok
244	7337	Hedwig	ok
251	7340	Hedwig	Gutter / Flashing
245	7343	Hedwig	Siding
250	7344	Hedwig	okl
249	7348	Hedwig	Back Lanai Roof off / Storm Shutter
246	7349	Hedwig	Carport Gone
248	7354	Hedwig	Dish bent
247	7355	Hedwig	ok

<b>ID #</b>	<b>Address</b>	<b>Street</b>	<b>Damage Assessment</b>
<b>377</b>	<b>7360</b>	<b>Heston</b>	Lattice / Flashing
<b>350</b>	<b>7361</b>	<b>Heston</b>	ok
<b>376</b>	<b>7364</b>	<b>Heston</b>	ok
<b>351</b>	<b>7367</b>	<b>Heston</b>	ok
<b>375</b>	<b>7368</b>	<b>Heston</b>	Lattice
<b>374</b>	<b>7372</b>	<b>Heston</b>	ok
<b>352</b>	<b>7373</b>	<b>Heston</b>	ok
<b>373</b>	<b>7376</b>	<b>Heston</b>	Flashing
<b>353</b>	<b>7377</b>	<b>Heston</b>	ok
<b>372</b>	<b>7380</b>	<b>Heston</b>	ok
<b>354</b>	<b>7381</b>	<b>Heston</b>	ok
<b>371</b>	<b>7384</b>	<b>Heston</b>	Lanai Screen
<b>355</b>	<b>7385</b>	<b>Heston</b>	ok
<b>370</b>	<b>7388</b>	<b>Heston</b>	ok
<b>356</b>	<b>7389</b>	<b>Heston</b>	Palm tree down
<b>369</b>	<b>7392</b>	<b>Heston</b>	ok
<b>357</b>	<b>7393</b>	<b>Heston</b>	ok
<b>368</b>	<b>7396</b>	<b>Heston</b>	ok
<b>358</b>	<b>7397</b>	<b>Heston</b>	ok
<b>367</b>	<b>7400</b>	<b>Heston</b>	Lanai Screen
<b>359</b>	<b>7401</b>	<b>Heston</b>	Flashing
<b>366</b>	<b>7404</b>	<b>Heston</b>	ok
<b>360</b>	<b>7405</b>	<b>Heston</b>	ok
<b>365</b>	<b>7408</b>	<b>Heston</b>	ok
<b>361</b>	<b>7411</b>	<b>Heston</b>	ok
<b>364</b>	<b>7412</b>	<b>Heston</b>	Screen / Lattice / Fence
<b>362</b>	<b>7415</b>	<b>Heston</b>	ok
<b>363</b>	<b>7416</b>	<b>Heston</b>	ok

<b>ID #</b>	<b>Address</b>	<b>Street</b>	<b>Damage Assessment</b>
220	7300	Lares	ok
219	7304	Lares	ok
218	7308	Lares	Fence / Steps
217	7312	Lares	ok
198	7313	Lares	ok
216	7316	Lares	ok
199	7317	Lares	ok
215	7320	Lares	ok
200	7321	Lares	Tree
214	7324	Lares	Skirting
201	7327	Lares	ok
213	7328	Lares	ok
212	7332	Lares	ok
202	7333	Lares	ok
211	7336	Lares	ok
203	7337	Lares	ok
210	7340	Lares	ok
204	7341	Lares	ok
209	7344	Lares	ok
208	7348	Lares	Debris
205	7349	Lares	Tree
207	7352	Lares	ok
206	7353	Lares	ok

<b>ID #</b>	<b>Address</b>	<b>Street</b>	<b>Damage Assessment</b>
326	7384	Longmont	ok
301	7385	Longmont	Flashing / Roof
325	7388	Longmont	ok
324	7392	Longmont	Lanai Screen
302	7393	Longmont	Skirting
323	7396	Longmont	ok
303	7397	Longmont	Skirting
322	7400	Longmont	ok
304	7403	Longmont	ok
321	7404	Longmont	Lime Tree Down
305	7407	Longmont	Skirting
320	7408	Longmont	Skirting
306	7411	Longmont	ok
319	7412	Longmont	Lattice / Skirting
307	7415	Longmont	ok
318	7416	Longmont	ok
308	7421	Longmont	Skirting
309	7425	Longmont	Fence / Skirting
310	7429	Longmont	ok
311	7433	Longmont	ok
312	7437	Longmont	Roof, flashing
313	7441	Longmont	ok
314	7445	Longmont	ok
315	7449	Longmont	ok
316	7453	Longmont	ok
317	7457	Longmont	ok

<b>ID #</b>	<b>Address</b>	<b>Street</b>	<b>Damage Assessment</b>
<b>280</b>	<b>7361</b>	<b>Petula</b>	Siding
<b>281</b>	<b>7365</b>	<b>Petula</b>	ok
<b>282</b>	<b>7369</b>	<b>Petula</b>	ok
<b>283</b>	<b>7373</b>	<b>Petula</b>	ok
<b>284</b>	<b>7377</b>	<b>Petula</b>	ok
<b>285</b>	<b>7381</b>	<b>Petula</b>	ok
<b>286</b>	<b>7385</b>	<b>Petula</b>	ok
<b>287</b>	<b>7389</b>	<b>Petula</b>	ok
<b>288</b>	<b>7393</b>	<b>Petula</b>	Fence / Trees
<b>289</b>	<b>7397</b>	<b>Petula</b>	ok
<b>290</b>	<b>7401</b>	<b>Petula</b>	ok
<b>291</b>	<b>7405</b>	<b>Petula</b>	okl
<b>292</b>	<b>7409</b>	<b>Petula</b>	ok
<b>300</b>	<b>7412</b>	<b>Petula</b>	Downspout
<b>293</b>	<b>7413</b>	<b>Petula</b>	ok
<b>299</b>	<b>7416</b>	<b>Petula</b>	Lanai door / vinyl window / Skirting
<b>294</b>	<b>7417</b>	<b>Petula</b>	ok
<b>298</b>	<b>7420</b>	<b>Petula</b>	ok
<b>295</b>	<b>7421</b>	<b>Petula</b>	Siding loose
<b>297</b>	<b>7424</b>	<b>Petula</b>	Siding loose
<b>296</b>	<b>7425</b>	<b>Petula</b>	Carport gone, Palm tree down

<b>ID #</b>	<b>Address</b>	<b>Street</b>	<b>Damage Assessment</b>
<b>33</b>	<b>7490</b>	<b>Ratan</b>	Clothesline
<b>1</b>	<b>7491</b>	<b>Ratan</b>	Tree Branches
<b>34</b>	<b>7494</b>	<b>Ratan</b>	Golf Cart Cover
<b>35</b>	<b>7498</b>	<b>Ratan</b>	ok
<b>2</b>	<b>7499</b>	<b>Ratan</b>	Carport, Lattice, Major Tree Damage
<b>36</b>	<b>7502</b>	<b>Ratan</b>	Fascia - Tree Down
<b>37</b>	<b>7506</b>	<b>Ratan</b>	ok
<b>3</b>	<b>7507</b>	<b>Ratan</b>	Siding
<b>38</b>	<b>7510</b>	<b>Ratan</b>	ok
<b>4</b>	<b>7511</b>	<b>Ratan</b>	Screen lanai & tree uprooted
<b>39</b>	<b>7514</b>	<b>Ratan</b>	ok
<b>5</b>	<b>7515</b>	<b>Ratan</b>	ok
<b>40</b>	<b>7518</b>	<b>Ratan</b>	Skirting
<b>6</b>	<b>7519</b>	<b>Ratan</b>	ok
<b>7</b>	<b>7523</b>	<b>Ratan</b>	ok
<b>41</b>	<b>7524</b>	<b>Ratan</b>	ok
<b>8</b>	<b>7527</b>	<b>Ratan</b>	ok
<b>42</b>	<b>7530</b>	<b>Ratan</b>	Skirting
<b>9</b>	<b>7531</b>	<b>Ratan</b>	ok
<b>43</b>	<b>7534</b>	<b>Ratan</b>	ok
<b>10</b>	<b>7535</b>	<b>Ratan</b>	Carport screen, lattice
<b>44</b>	<b>7538</b>	<b>Ratan</b>	Siding
<b>11</b>	<b>7539</b>	<b>Ratan</b>	ok
<b>45</b>	<b>7542</b>	<b>Ratan</b>	ok
<b>12</b>	<b>7543</b>	<b>Ratan</b>	ok
<b>13</b>	<b>7547</b>	<b>Ratan</b>	ok
<b>46</b>	<b>7548</b>	<b>Ratan</b>	ok
<b>14</b>	<b>7551</b>	<b>Ratan</b>	ok
<b>47</b>	<b>7554</b>	<b>Ratan</b>	ok
<b>15</b>	<b>7555</b>	<b>Ratan</b>	ok
<b>48</b>	<b>7558</b>	<b>Ratan</b>	ok
<b>16</b>	<b>7559</b>	<b>Ratan</b>	ok
<b>49</b>	<b>7562</b>	<b>Ratan</b>	ok
<b>50</b>	<b>7566</b>	<b>Ratan</b>	Skirting / Antenna
<b>17</b>	<b>7567</b>	<b>Ratan</b>	Tree / Eebris

<b>ID #</b>	<b>Address</b>	<b>Street</b>	<b>Damage Assessment</b>
51	7570	Ratan	Siding into Shed
52	7574	Ratan	ok
53	7578	Ratan	ok
54	7582	Ratan	ok
55	7586	Ratan	Bad Shingle Damage
18	7587	Ratan	Lanai Roof
56	7590	Ratan	Lanai / Fence
19	7591	Ratan	ok
57	7594	Ratan	
20	7595	Ratan	ok
58	7598	Ratan	Golf Cart Cover
21	7599	Ratan	Skirting
22	7603	Ratan	ok
59	7604	Ratan	ok
23	7607	Ratan	ok
60	7610	Ratan	ok
24	7611	Ratan	ok
61	7614	Ratan	ok
25	7615	Ratan	ok
62	7618	Ratan	ok
26	7619	Ratan	ok
63	7622	Ratan	ok
27	7623	Ratan	ok
28	7627	Ratan	ok
64	7628	Ratan	ok
29	7631	Ratan	ok
65	7634	Ratan	Downspout / Tree Down
30	7635	Ratan	Tree
66	7638	Ratan	ok
31	7639	Ratan	ok
67	7642	Ratan	Lampost
32	7643	Ratan	ok
68	7646	Ratan	ok
69	7650	Ratan	Siding / Antenna off / Front door
70	7654	Ratan	ok

<b>ID #</b>	<b>Address</b>	<b>Street</b>	<b>Damage Assessment</b>
<b>495</b>	<b>7400</b>	<b>Sidi</b>	Siding / Roof
<b>500</b>	<b>7401</b>	<b>Sidi</b>	Flashing down
<b>496</b>	<b>7404</b>	<b>Sidi</b>	ok
<b>497</b>	<b>7408</b>	<b>Sidi</b>	Lattice / Fence
<b>499</b>	<b>7409</b>	<b>Sidi</b>	Skirting loose
<b>498</b>	<b>7412</b>	<b>Sidi</b>	ok



<b>ID #</b>	<b>Address</b>	<b>Street</b>	<b>Damage Assessment</b>
475	7450	Silage	Lanai Screen
505	7451	Silage	ok
474	7454	Silage	ok
504	7455	Silage	ok
473	7458	Silage	Screen
503	7459	Silage	ok
472	7462	Silage	ok
471	7466	Silage	
470	7470	Silage	ok
469	7474	Silage	ok
468	7478	Silage	Screen
502	7479	Silage	ok
467	7482	Silage	Tree uprooted / Shutter / Flashing
501	7483	Silage	Siding
466	7486	Silage	Lanai Window Out
465	7490	Silage	ok
464	7494	Silage	Skirting
463	7498	Silage	ok
462	7502	Silage	Trellis
461	7506	Silage	ok
460	7510	Silage	ok
459	7514	Silage	ok
458	7518	Silage	ok
457	7522	Silage	Skirting
494	7523	Silage	ok
456	7526	Silage	Lanai Screen
493	7527	Silage	Skirting
455	7530	Silage	ok
492	7531	Silage	ok
454	7534	Silage	Skirting
491	7535	Silage	Front shutters
453	7538	Silage	ok
490	7539	Silage	Lanai Window
452	7546	Silage	Lanai screen out / Siding
451	7550	Silage	ok

<b>ID #</b>	<b>Address</b>	<b>Street</b>	<b>Damage Assessment</b>
450	7554	Silage	ok
449	7558	Silage	ok
489	7559	Silage	Roof film loose
448	7562	Silage	Gutters & Downspouts
488	7563	Silage	ok
447	7566	Silage	Siding loose
487	7567	Silage	ok
446	7570	Silage	Screen / Skirting
486	7571	Silage	Awning / Lattice
445	7574	Silage	Downspout / Screen Door
485	7575	Silage	Water Heating Siding gone
444	7578	Silage	Screen missing
484	7579	Silage	Siding / Flashing
483	7583	Silage	Carport peeled back / Fence
443	7586	Silage	Skirting
482	7587	Silage	okl
442	7590	Silage	ok
481	7591	Silage	Tree down
441	7598	Silage	Fence
480	7599	Silage	Uprooted tree
440	7602	Silage	Flashing
479	7603	Silage	ok
439	7610	Silage	ok
478	7611	Silage	ok
438	7614	Silage	ok
437	7618	Silage	ok
477	7619	Silage	ok
436	7622	Silage	Skirting
435	7626	Silage	ok
476	7627	Silage	Tree

<b>ID #</b>	<b>Address</b>	<b>Street</b>	<b>Damage Assessment</b>
<b>172</b>	<b>7328</b>	<b>Swinton</b>	ok
<b>173</b>	<b>7329</b>	<b>Swinton</b>	ok
<b>174</b>	<b>7333</b>	<b>Swinton</b>	ok
<b>171</b>	<b>7334</b>	<b>Swinton</b>	ok
<b>175</b>	<b>7337</b>	<b>Swinton</b>	ok
<b>170</b>	<b>7340</b>	<b>Swinton</b>	
<b>176</b>	<b>7341</b>	<b>Swinton</b>	ok
<b>169</b>	<b>7344</b>	<b>Swinton</b>	ok
<b>177</b>	<b>7345</b>	<b>Swinton</b>	ok
<b>168</b>	<b>7348</b>	<b>Swinton</b>	ok
<b>178</b>	<b>7349</b>	<b>Swinton</b>	ok
<b>167</b>	<b>7352</b>	<b>Swinton</b>	ok
<b>179</b>	<b>7353</b>	<b>Swinton</b>	Facia
<b>166</b>	<b>7356</b>	<b>Swinton</b>	ok
<b>180</b>	<b>7357</b>	<b>Swinton</b>	ok
<b>165</b>	<b>7360</b>	<b>Swinton</b>	Front trim
<b>181</b>	<b>7361</b>	<b>Swinton</b>	ok
<b>182</b>	<b>7365</b>	<b>Swinton</b>	ok
<b>164</b>	<b>7366</b>	<b>Swinton</b>	ok
<b>183</b>	<b>7369</b>	<b>Swinton</b>	Screen
<b>163</b>	<b>7372</b>	<b>Swinton</b>	Carport / Tree
<b>184</b>	<b>7373</b>	<b>Swinton</b>	ok
<b>185</b>	<b>7377</b>	<b>Swinton</b>	ok
<b>162</b>	<b>7378</b>	<b>Swinton</b>	ok
<b>186</b>	<b>7381</b>	<b>Swinton</b>	ok
<b>161</b>	<b>7384</b>	<b>Swinton</b>	ok
<b>187</b>	<b>7385</b>	<b>Swinton</b>	ok

<b>ID #</b>	<b>Address</b>	<b>Street</b>	<b>Damage Assessment</b>
<b>188</b>	<b>7300</b>	<b>Thor</b>	ok
<b>189</b>	<b>7304</b>	<b>Thor</b>	ok
<b>190</b>	<b>7308</b>	<b>Thor</b>	Skirting
<b>197</b>	<b>7309</b>	<b>Thor</b>	ok
<b>191</b>	<b>7312</b>	<b>Thor</b>	Window
<b>196</b>	<b>7313</b>	<b>Thor</b>	ok
<b>192</b>	<b>7316</b>	<b>Thor</b>	ok
<b>195</b>	<b>7317</b>	<b>Thor</b>	ok
<b>193</b>	<b>7320</b>	<b>Thor</b>	ok
<b>194</b>	<b>7321</b>	<b>Thor</b>	ok

<b>ID #</b>	<b>Address</b>	<b>Street</b>	<b>Damage Assessment</b>
<b>551</b>	<b>7340</b>	<b>Tisa</b>	ok
<b>550</b>	<b>7344</b>	<b>Tisa</b>	Screens
<b>506</b>	<b>7345</b>	<b>Tisa</b>	Skirting / Fence
<b>549</b>	<b>7348</b>	<b>Tisa</b>	ok
<b>548</b>	<b>7352</b>	<b>Tisa</b>	Loose skirting & siding / Storage Bin Open
<b>507</b>	<b>7353</b>	<b>Tisa</b>	Siding
<b>547</b>	<b>7356</b>	<b>Tisa</b>	ok
<b>508</b>	<b>7357</b>	<b>Tisa</b>	Shutter off
<b>546</b>	<b>7360</b>	<b>Tisa</b>	Skirting
<b>509</b>	<b>7361</b>	<b>Tisa</b>	ok
<b>545</b>	<b>7364</b>	<b>Tisa</b>	ok
<b>510</b>	<b>7365</b>	<b>Tisa</b>	ok

<b>ID #</b>	<b>Address</b>	<b>Street</b>	<b>Damage Assessment</b>
<b>150</b>	<b>7300</b>	<b>Varley</b>	Roof
<b>149</b>	<b>7304</b>	<b>Varley</b>	Screen Lanai
<b>148</b>	<b>7308</b>	<b>Varley</b>	Screen Lanai
<b>147</b>	<b>7312</b>	<b>Varley</b>	ok
<b>146</b>	<b>7316</b>	<b>Varley</b>	ok
<b>145</b>	<b>7320</b>	<b>Varley</b>	ok
<b>144</b>	<b>7324</b>	<b>Varley</b>	ok
<b>143</b>	<b>7328</b>	<b>Varley</b>	Downspout / Skirting
<b>151</b>	<b>7329</b>	<b>Varley</b>	ok
<b>142</b>	<b>7332</b>	<b>Varley</b>	Carport roof peeled back
<b>152</b>	<b>7333</b>	<b>Varley</b>	ok
<b>153</b>	<b>7337</b>	<b>Varley</b>	ok
<b>141</b>	<b>7338</b>	<b>Varley</b>	ok
<b>154</b>	<b>7341</b>	<b>Varley</b>	ok
<b>140</b>	<b>7344</b>	<b>Varley</b>	ok
<b>155</b>	<b>7345</b>	<b>Varley</b>	ok
<b>156</b>	<b>7349</b>	<b>Varley</b>	ok
<b>139</b>	<b>7350</b>	<b>Varley</b>	ok
<b>157</b>	<b>7353</b>	<b>Varley</b>	ok
<b>138</b>	<b>7356</b>	<b>Varley</b>	ok
<b>158</b>	<b>7357</b>	<b>Varley</b>	ok
<b>137</b>	<b>7360</b>	<b>Varley</b>	ok
<b>159</b>	<b>7361</b>	<b>Varley</b>	ok
<b>136</b>	<b>7364</b>	<b>Varley</b>	Back window out / Siding
<b>160</b>	<b>7365</b>	<b>Varley</b>	ok
<b>135</b>	<b>7368</b>	<b>Varley</b>	ok
<b>134</b>	<b>7372</b>	<b>Varley</b>	ok
<b>133</b>	<b>7376</b>	<b>Varley</b>	ok
<b>132</b>	<b>7380</b>	<b>Varley</b>	ok
<b>131</b>	<b>7384</b>	<b>Varley</b>	Screen
<b>130</b>	<b>7388</b>	<b>Varley</b>	Facia

<b>ID #</b>	<b>Address</b>	<b>Street</b>	<b>Damage Assessment</b>
<b>101</b>	<b>7400</b>	<b>Widness</b>	ok
<b>100</b>	<b>7404</b>	<b>Widness</b>	ok
<b>99</b>	<b>7408</b>	<b>Widness</b>	ok
<b>98</b>	<b>7412</b>	<b>Widness</b>	ok
<b>97</b>	<b>7416</b>	<b>Widness</b>	ok
<b>96</b>	<b>7420</b>	<b>Widness</b>	
<b>95</b>	<b>7424</b>	<b>Widness</b>	ok
<b>102</b>	<b>7427</b>	<b>Widness</b>	ok
<b>94</b>	<b>7428</b>	<b>Widness</b>	Debris
<b>93</b>	<b>7432</b>	<b>Widness</b>	ok
<b>103</b>	<b>7433</b>	<b>Widness</b>	ok
<b>92</b>	<b>7436</b>	<b>Widness</b>	ok
<b>104</b>	<b>7437</b>	<b>Widness</b>	ok
<b>91</b>	<b>7440</b>	<b>Widness</b>	Fascia
<b>105</b>	<b>7441</b>	<b>Widness</b>	ok
<b>90</b>	<b>7444</b>	<b>Widness</b>	ok
<b>106</b>	<b>7445</b>	<b>Widness</b>	ok
<b>107</b>	<b>7449</b>	<b>Widness</b>	Lattice / Fence
<b>108</b>	<b>7453</b>	<b>Widness</b>	Tree on Car
<b>89</b>	<b>7456</b>	<b>Widness</b>	ok
<b>109</b>	<b>7457</b>	<b>Widness</b>	Tree leaning